

Carpenters Works done for Her Royal
Highness Princess Dowager of Wales in
Gardens at New from Michlemas to Xmas, 1760
1760
J Geo: Warren

Oct. 8 th	To the Stages in the Green house & putt up shelves in the Windows &c 2 Men 6 Days Ea- 1.. 10.. 0	
	To the posts & Rails in Archa	
21 st	10 f. of Single g. 1 C of 20. W. 2 Days Works - 0.. 7.. 10	
	To Moving the planks & Blocks &c in the Green house 2 Men 1 1/2 Day Each - 0.. 7.. 6	
	To putt up the Lights over the pits in front of Loticks hothouse & Taking down Shades &c. -	
	2 Men 1/2 Day Each. - 0.. 7.. 6	
	To the Shelves for Loticks hothouse	
	60 f. of Batten & 2 Men 1 Day Each. - 0.. 15.. 0	
	To Repairing the fences Round Trees & the fence by the ponds side &c	
	44 f. of Split Balks - 0.. 3.. 0	
	2 C of 10. 1 1/2 C of 20. W. 1 1/2 C of Wood W. - 0.. 4.. 10	
	2 Men 2 1/2 Days Each. - 0.. 12.. 6	
1-4 2-6	To Repairing the Lathing at the Aviary &c	
	1 1/2 Dozen of Spantile Laths. - 0.. 3.. 0	
	2 C of C. W. 1 1/2 C of Beads 2 Men 1 Day Ea- 0.. 6.. 9	
2/22 nd	To Lotick hothouse 10 f. of whole Deal. - 0.. 2.. 6	
	To Repairing the fences round Trees &c	
	80 f. of Split Balks - 0.. 7.. 4	
	2 C of 10. 1 1/2 C of 20. 3 C of C. W. - 0.. 4.. 10	
	2 Men 3 1/2 Days Each. - 0.. 17.. 6	
	To Casing the Lashes & Doors at the Green house 2 Men 3 Days Each. - 0.. 15.. 0	
	To Repairing the fence by the ponds side	
	12 f. of Single g. 12 f. of whole Deal - 0.. 4.. 0	
	3 C of C. W. 2 Men 3 Days Each. - 0.. 16.. 6	
	Car. over - 0.. 6.. 3	

	Rec'd over	0.. 6.. 3
	To Repairing the planking & Lathing at Aviary 1 Dozen of portable Laths	0.. 2.. 0
	4 C of Spikes 1/2 C of 20. W. 1 C of boat W.	0.. 5.. 0
	2 Men 2 Days Each.	0.. 10.. 0
	To the posts & Rails in Aha.	
	3 Days Work.	0.. 7.. 6
29 th	To Lotick's hothouse To fixing the planks for the Coals 12 ft. of inch 1/2 planks.	0.. 3.. 6
	To D. & putt up Shelves & other jobs 12 ft. of 1/2 Deal 1 C of 20. 1/2 C of 10. W.	0.. 3.. 10
	2 Men 3 1/2 Days Each.	0.. 17.. 6
	To the posts & Rails in Aha	
	32 ft. of inch 1/2 Deal 6 in wide	0.. 5.. 2
	37 ft. of ft. of 1/2 3.	0.. 6.. 2
	1 C of 20. & 4 C of Spikes.	0.. 4.. 0
	2 Men 4 1/2 Days Each.	1.. 2.. 6
Nov. 5 th	To the posts & Rails in Aha.	
	24 ft. of ft. of 1/2 3.	0.. 4.. 0
	14 ft. of inch 1/2 Deal 6 in wide.	0.. 2.. 4
	1 C of 20. 1 C of 10. W. 4 C of Spikes	0.. 4.. 0
	2 Men 5 Days Each.	1.. 5.. 0
	To Making a packing Box for W. Noyton	
	1/10 ft. Leaf Pit Deal 3/4 C of 6. W.	0.. 1.. 4 1/2
	1/2 a Days Work.	0.. 1.. 3
	To hanging a Gate & Mend 3 rails for Allen.	
	1 C of 10. W. 1 Days Work.	0.. 3.. 2
	To Mend the Flower Stand Easing doors & gates &c 12 ft. of whole Deal.	0.. 3.. 0
	1 C of 10. 1 C of 6. W. & 4 Large Screws.	0.. 1.. 6
	1 1/2 Days Work.	0.. 3.. 4
7 th 12.	To putt on Covers to plants in Lotick's Garden	
	1 Dozen of portable Laths	0.. 2.. 0
	2 C of 20. 2 C of 10. W. 12 Large hold fasts	0.. 0.. 0
	2 Men 3 1/2 Days Each.	0.. 17.. 6
	Car. on	16.. 10.. 11 1/2

3
0
0
0
6
6
10
6
2
2
0
6
0
4
0
0
4
3
2
0
6
4
0
0
6
11/2

96 ft of Deal in 1/2 Lf for Mr. Ryton used 16. 10. 11/2
 To Mend the Beavers at the pine house 0. 4. 0
 putt on fastenings & other jobs
 12 ft of whole Deal 0. 3. 0
 1 C of 20. 1/2 C of 10. 1 C of 6. W. 0. 2. 10
 5 Days Work. 0. 12. 6
 To Repairing the pine house & altering
 the frames at the pits & other jobs.
 2/12 ft. Leaves of Split Deal 0. 2. 4
 4/12 ft. whole Deals. 12 ft. of f. g. 4 1/2 3 0. 10. 0
 1/2 C of 20. 1/2 C of 10. W. 12 Large hold fasts 0. 12. 0
 36 Large Screw Eyes
 2 Men 4 Days Each. 1. 0. 0
 To putt Covers over plants in Lotick Garden
 1 Dozen of pantile Laths 0. 2. 0
 2/12 ft. whole Deals 0. 4. 4
 18 Large hold fasts & W. 0. 6. 0
 1/2 C of 20. 1/2 C of 10. W. 1 C of boat W. 0. 4. 3
 1/2 C of Coat W.
 3/2 Days Work. 0. 8. 9
 To Mend the flower Stand Easing
 Doors & other jobs. 12 ft. of whole Deal 0. 3. 0
 1 C of 10. 1/2 C of 6. W. 6 hold fasts. 0. 2. 5
 1/2 Days Work. 0. 3. 9
 To putt Covers over the plants in
 Lotick Garden 1 Dozen of pantile Laths 0. 2. 0
 12 hold fasts 1/2 C of 20. 1 C of 10. W. 0. 7. 10
 1 C of boat W. 1 C of tenter hooks
 To putt up Racks in the Shed to hang
 Matts on & Repairing a gate & 4 Days 0. 10. 0
 To the Aviary To fastening the Ratt
 and hanging a Door & other jobs.
 Car. over 22. 12. 7 1/2

7/19th

7/26th

3
0
0
0
6
6
10
6
2
2
0
6
0
4
0
0
4
3
2
0
6
4
0
0
6
11/2

96 ft of Deal in 1/2 of for Mr. Ryton used 16. 10. 11/2
 To Mend the Beavers at the pine house 0. 4. 0
 putt on fastenings & other jobs
 12 ft of whole Deal 0. 3. 0
 1 C of 20. 1/2 C of 10. 1 C of 6. W. 0. 2. 10
 5 Days Work. 0. 12. 6
 To Repairing the pine house & altering
 the frames at the pits & other jobs.
 2/12 ft. Leaves of Split Deal 0. 2. 4
 4/12 ft. whole Deals. 12 ft. of fine. 4 1/2 0. 10. 0
 1/2 C of 20. 1/2 C of 10. W. 12 Large hold fast. } 0. 12. 0
 36 Large Screw Eyes }
 2 Men 4 Days Each. 1. 0. 0
 To putt Covers over plants in Lotick Garden
 1 Dozen of pantile Laths 0. 2. 0
 2/12 ft. whole Deals 0. 4. 4
 18 Large hold fast. & W. 0. 6. 0
 1/2 C of 20. 1/2 C of 10. W. 1 C of boat W. } 0. 4. 3
 1/2 C of Coat W. }
 3/2 Days Work. 0. 8. 9
 To Mend the flower Stand Easing
 Doors & other jobs. 12 ft. of whole Deal 0. 3. 0
 1 C of 10. 1/2 C of 6. W. 6 hold fast. 0. 2. 5
 1/2 Days Work. 0. 3. 9
 To putt Covers over the plants in
 Lotick Garden 1 Dozen of pantile Laths 0. 2. 0
 12 hold fast. 1/2 C of 20. 1 C of 10. W. } 0. 7. 10
 1 C of boat W. 1 C of tenter hooks }
 To putt up Racks in the Shed to hang
 Matts on & Repairing a gate & 4 Days 0. 10. 0
 To the Aviary To fastening the Ratt
 and hanging a Door & other jobs.
 Car. over 22. 12. 7 1/2

7/19th

7/26th

	Nov. over	22. 12. 7 1/2
a pair of Hinges & W.		0. 1. 0
6 pantile Laths 1/2 C of 10. W.		
6 C of Fenter hooks & Days Work.		0. 12. 5
To Mend the fences Round Tans & Easing Doors & Lashes at Green house &c		
1 C of Boards 1/2 C of Board W.		0. 2. 0
12 f. of whole Deal & 25 f. of Split Balk		0. 5. 0
2 Men 2 Days Each.		0. 10. 0
Dec. 3. To the pine house		
1 Dozen of 12 f. Laths inch 1/2 Square		0. 5. 0
1/2 C of 20. 1/2 C of 10. W. 1 Days Work		0. 3. 7
To Mend the Door at the old Greenhouse		
1/2 C of 10. W. 1/2 a Days Work.		0. 1. 0
To gett & Stuff Ready for Staking Trees		
40 f. of whole Balks.		0. 6. 0
36 f. of whole Deal.		0. 4. 0
2 Men 2 1/2 Days Each.		0. 12. 6
To the Manazery		
1 Large & Garnet henge & Screws & Lab.		0. 2. 7 1/2
To the posts & Rails in Akah.		
20 f. of Fir g. 4 & 3.		0. 3. 4
30 f. of whole Deal 12 f. of 1/4 D.		0. 9. 0
1/2 C of 20. W. 2 Men 4 Days Each.		1. 2. 0
Jan. 10. To Hoaring the hot Walls & other jobs		
2 C of 20. 1 C of 10. W. 2 Men 2 Days Ea.		0. 13. 6
To Mend the Rails in Cowfield		
44 f. of Split Balks 7 D of Spikes		0. 10. 10
To Easing Gates & putt on Locks. 2 a Day		0. 1. 3
To the posts & Rails in Akah		
20 f. of Fir g. 4 & 3. 12 f. of whole Deal		0. 6. 4
8 D of White Lead 1 Quart of Oyl.		0. 5. 6
2 C of 20. 1 C of 10. W. 6 D of Spikes		0. 6. 6
2 Men 4 Days Each.		1. 0. 0
Car. on		31. 2. 4

7 1/2
0
5
0
0
0
0
7
0
0
6
7 1/2
4
0
0
6
10
3
4
6
6
0
4

9/17th

To the posts & Rails in Akah
 2 Men 1/2 Day Each. ————— 0.. 7.. 6

To Mend 9 frames in Lotick Garden and
 putt 9 frames over plants & other jobs
 12 f. of feather edged Batten ————— 0.. 1.. 0

1/2 Dozen of pantile Laths ————— 0.. 3.. 0

6 f. of 2 1/2 Deal & 14 f. of D. 2 1/2 Sof. — 0.. 3.. 2

1/2 C of 10. 1/2 C of 6. W. 3 C of Tenter hooks 0.. 5.. 0

2 Men 3 Days Each. ————— 0.. 15.. 0

To the hot Wall in Kitchen Garden
 27 f. of Deal 2 1/2 Square ————— 0.. 2.. 3

12 f. of whole Deal 1 C of 20. W. — 0.. 4.. 4

To D. & Mend the Shutters at the old
 Green house 2 Men 1 Day Each. — 0.. 5.. 0

To Gett of Inf. Ready to Stake Trees
 36 f. of whole Deal ————— 0.. 9.. 0

18 f. of f. of 3 & 3. ————— 0.. 2.. 3

44 f. of Split Balk. ————— 0.. 5.. 4

2 Men 2 1/2 Days Each. ————— 0.. 12.. 6

To Mend 9 Feeding Boxes for Allen
 1 C of 6. W. 1/2 C of Board W. — 0.. 1.. 0

a pair of Dovetailed hinges & 2 f. of Wire — 0.. 1.. 2

1 Days Works. ————— 0.. 2.. 6

9/24th

To Repairing the Rails in Cowfield
 22 f. of Balk 1 C of 20. W. 2 Spikes — 0.. 6.. 0

2 Men 1 Day Each. ————— 0.. 5.. 0

To Casing the Lashes at the Greenhouse
 2 Gates Next the Road Casing Gates &
 Doors in Flower Garden &c
 1 C of 10. W. 1 C of Board — 0.. 1.. 4

2 Men 2 Days Each. ————— 0.. 10.. 0

To the Posts & Rails in Akah
 Car. over ————— 36.. 5.. 4

		Rec ^d over	36.5.4
	10 ft ⁴ of inch ¹ / ₂ Deal 12 ft ⁴ of 2 ¹ / ₂ Deal 4 wide		0.7.0
	12 ft ⁴ of 3/4 in. 3 ft 3.		0.1.6
	1 C of 20. W. & 60 Spikes.		0.6.4
	2 Men 5 Days Each.		1.5.0
712. 6	N. 25 Three Light Mellon frames Sup. white Deal plain both Sides Dovetailed at the Angles & Channels for Water	at 8.	23.15.0
58. 4	Sup. 3/4 Deal parting pieces at 5		1.4.3
2. 1	Cube oak to angle pieces	at 4.0	0.2.4
432. 0	N. 24 Covers for W. Antons frames Sup. Sit Deal plain both Sides Grooved & Ledged.	at 4 1/2	7.5.4
492. 0	Runn ^g of Fillet over Joynets at 1/2		1.0.6
	N. 40 handles 4 ft 10 in Long Each whole Deal.	at	0.16.0
	Paint to putt D. together		0.5.0
	To painting 12 of D. twice over		0.10.0

Jan^y 12th Exam^d W Chambers (O.S.) 73.17.7

Rec^d Jan^y 21. 1760 of Her Royal
Highness Princess Dowager of Wales
by the hands of W^m Chambers Esq^r
the full Contents of this Bill

73.17.7 J^s Geo. Warren

4
0
6
4
0

0
3
4

4
6

0

0

0

7

Warren Jayminter
Es. 73. 17. 7