

Carpenters Works Done for Her Royal Highness Princess Dowager of Wales, in Gardens at Tew from Midsummer to Michlemas 1769

J. Geo. Warren

1769
July

To the Stage in Lotick Lathouse &c			
24 f. of 2 1/2 Deal		0..	0.. 0
14 f. of 3/4 Deal to Windows in Back Shed		0..	1.. 9
1 C of 20. 1 C of 6. W. 2 Days Work		0..	6.. 10
To Repairing 2 Gates at the upper end of Garden the Gate by the Duke the Gate by the poor house &c			
12 f. of whole Deal 12 f. of Split Deal		0..	4.. 0
1 C of 10. 1 C of 6. W. 4 C of Tenter hooks.		0..	5.. 4
2 Men 1/2 Day Each.		0..	7.. 6
To Repairing Lathing at Manazery. Repairing & hanging 2 Gates & Mending the Rails in the Courtfield &c			
1 Dozen of pantile Laths.		0..	2.. 0
24 f. of whole Deal 10 f. of Split Deal		0..	7.. 6
60 f. of Split Board		0..	5.. 0
1/2 C of 20. 1 C of 10. 1/2 C of 6. W.			
2 C of Board W. 12 Spikes 6 C of Pitch		0..	0.. 1
2 Men 3 Days Each.		0..	15.. 0
To Mending Doors & frames Casings Lights & Repairing frames in Kitchen Garden &c			
12 f. of whole Deal 12 f. of Elm Board.		0..	6.. 0
1 C of 20. 1/2 C of 10. W.		0..	2.. 7
2 Men 1 Day Each		0..	5.. 0
To Repairing the Minarets at the Mosque			
3/12 f. Boards 12 f. of 2 1/2 Deal.		0..	0.. 6
1/2 C of 20. 1 C of 10. 1 C of 6. W. 2 C of Boards.		0..	4.. 4
7 B of Paint & 5 Days Work		0..	16.. 0
To Repairing the Window Linings at Pagoda			
12 f. of 3/4 Deal 1 C of Boards & 1 Days Work		0..	4.. 6
To Repairing the Rails in Akah & putting on Irons &c			
6 f. of iron 6 f. of 1/2		0..	2.. 0
1 Days Work		0..	2.. 6
To Repairing the Bridge 2 Men 1 Day Ea		0..	5.. 0
Car. over		6..	7.. 5

7 th	To Making a Box for Mr. Aiton & Taking the Light of the Pitts & 12 f th of whole Deal, 1 C of 10 th W.	Do. over	6.. 7.. 5
	2 Men 1 Day Each.		0.. 3.. 10
	To Mending the Rails in the Cowfield & fencing in the hay Rick & other jobs for Allen		0.. 5.. 0
	22 f th of Fir 4 & 3		0.. 13.. 0
	112 f th of Split Wale		0.. 9.. 4
	30 Spikes 1/2 C of 2 Shill W.		0.. 3.. 6
	1 C of 20 th W. 2 Men 1/2 Day Each		0.. 0.. 10
	2 Dozen of flower Sticks 3 f th Long		0.. 6.. 0
	Paint 1/2 3 times over		0.. 2.. 0
	To putt on a New Nett at Managery & Repairing the Ornaments & Lattings & 5 C of Tenterhooks		0.. 5.. 0
	3 Men 4 1/2 Days Each		1.. 13.. 9
9 th 15 th	To Repairing the Great Gates Next the Green & Sparring the Posts & 6 f th of oak of 6 1/2		0.. 3.. 0
	3 f th of Do oak		0.. 2.. 0
	4 Spikes 2 Men 1/2 Day Each.		0.. 2.. 10
	Taking Down the Ornaments to be painted putt ^g them up again & fastening the Nett & Several other jobs at Managery.		0.. 19.. 0
	1 C of Tenterhooks 2 Men 3 Days Each		1.. 13.. 4
	To Repairing the Chinese Bridge 20 f th of oak of 6 1/2 1/4 Ship Timber		0.. 10.. 0
	24 f th of Do 7 & 7		0.. 12.. 0
	36 f th of Double Deal		2.. 0.. 0
	30 Spikes 3 Men 5 Days Each.		0.. 0.. 2
	To Repairing the frames & Lights in Kitchen Garden & other jobs.		0.. 7.. 6
	24 f th of whole Deal, 1 C of 20 th W. 1 C of 10 th W.		0.. 0.. 2
	2 Men 1 1/2 Day Each.		0.. 7.. 6
12 th	To Repairing frames & Lights &c in Kitchen Garden		0.. 5.. 0
	24 f th of Split Deal 12 f th of whole Deal		0.. 1.. 7
	1 C of 10 th 1/2 C of 6 th W. 12 Wood Screws		10.. 10.. 9
	Car. on		

55631

Pro. on

5	2 Men 1 Day Each.	10.. 10.. 9
	To Several Repairs at Managery &c	0.. 5.. 0
10	12 Wood Saws 1 C of Coat W.	0.. 1.. 0
0	2 Men 1/2 Day Each	0.. 7.. 6
	To the Chinese Bridge & Repairing Fences	
	Round Bars & the Rails in Ahabaz &c	
	12 f. of Jug. 5 & 3/2	0.. 2.. 9
0	24 f. of whole Deal	0.. 6.. 0
4	1 C of 20. W. 12 Spikes	0.. 2.. 4
6	2 Men 6 Days Each.	1.. 10.. 0
10	To putt New Lines to the Light at Lotick	
0	hothouse	
0	N. 11 Coil of Rope weight 116 lb	4.. 16.. 0
	2 Men 2 1/2 Days Each	0.. 12.. 6
7. 29. #	To finishing the Lines at Lotick hothouse	
0	2 Men 2 Days Each.	0.. 10.. 0
9	To the Chinese Bridge	
	30 Spikes & Men 2 Days Each	0.. 12.. 6
	To Making good the quartering & Mending the	
0	Lathing & putt on a New Net at Managery	
0	20 f. of Jug. 4 & 1/2	0.. 4.. 2
10	1 Dozen of pantiler Laths	0.. 2.. 0
	12 f. of whole Deal 12 f. of Elm Board.	0.. 6.. 0
	1 C of 2 Shill. W. 1 C of 20. 1 C of 10. W.	} 0.. 10.. 5
	1/2 C of 6. W. 7 C of Tenter hooks	
0	3 Men 4 1/2 Days Each.	1.. 13.. 9
	To Mending the posts & Rails in Ahabaz & D	
4	over the Roundarch &c	
0	10 f. of whole Deal 12 f. of Double Deal	0.. 8.. 6
0	10 Spikes 1 C of 20. W.	0.. 2.. 10
0	2 Men 2 Days Each.	0.. 10.. 0
0	1/2 C of Tenter hooks for the gardeners use	0.. 1.. 6
Aug. 5. #	To Repairing the Doors & Door Cases at Managery	
	putt in New Sills & Repairing the Quartering	
2	Mending the Nets Mending & painting the	
6	Pearches & other jobs	
	36 f. of Jug. 4 & 1/2	0.. 7.. 6
0	1 Dozen of pantiler Laths	0.. 2.. 0
7	1 C of 20. 1 C of 10. W. 6 lb of Paint	0.. 5.. 2
9	Car. over	32.. 10.. 10

		Wro. over	
	1 C of Wood W. 24 Spikes		32. 10. 10
	2 Men 4 Days Each		0. 3. 0
	To the Rivary putt New Sills to the Doors & Mend of the Lathing & Easing Doors &c		1. 0. 0
	8 ft of fir of 6 @ 4		0. 2. 0
	1 C of 10. W. 1/2 C of Wood W. 1 Days Work		0. 3. 10
	To Repairing the Posts & Rails in Aha		0. 6. 6
	24 ft of fir of 5 @ 4		0. 4. 0
	24 ft of fir of 4 @ 3		0. 1. 6
	1 C of 10. 1/2 C of 20. W.		0. 7. 6
of 12. #	2 Men 1 1/2 Day Each		
	To Repairing & Pitching of Wind Troughs		
	Repairing the Lathing & Mend of Doors at Manazery & other Jobs		
	1 Dozen of portable Laths & D of Pitch		0. 4. 0
	12 ft of inch Deal		0. 2. 0
	2 C of Wood W. 1 C of 20. 1 C of 6. W. 1/2 C Boards		0. 4. 7
	2 Men 2 Days Each		0. 10. 0
	To the Manazery by Allens Mend of Doors & Pitching Troughs &c		
	1/2 C of Wood W. & D of pitch		0. 2. 3
	1 Days Work		0. 2. 6
	To Mend of the posts & Rails in Aha		
	12 ft of fir of 4 @ 3		0. 2. 0
	1/2 C of 2 Shill W. 1/2 C of 20. W.		0. 1. 0
	1 1/2 Days Work		0. 3. 9
	To Mend of the Pails by the Pond & fences round Trees, & a Water Parrow &c		
	3 C of Wood W. 1/4 C of 2 Shill W.		0. 3. 6
of 19 #	2 Men 2 Days Each		0. 10. 0
	To Mend of the posts & Rails in Aha		
	6 ft of fir of 6 @ 4 & 6 Spikes		0. 2. 6
	2 Men 1 Day Each		0. 5. 0
	To Making 2 Dozen of oak piles for Pond		
	96 ft of oak of 4 @ 3		1. 4. 0
	7 C of Large Center hooks		0. 7. 0
	2 Men 2 Days Each		0. 10. 0
	To Making a Box to Carry fruit in		
	12 ft of 1/2 Deal 1/2 C of Wood W.		0. 2. 0
	Car. on		39. 16. 7

10
0
0
0
0
10
6
0
6
6
0
0
7
0
3
6
0
0
9
6
0
6
0
0
0
0
0
0
0

	Angus hook & Eye		0.. 1.. 6
	1/2 Day's Work		0.. 1.. 3
	To Making Seed Boxes for Allen & Mendy Water Troughs & other Jobs in Aviary		0.. 7.. 6
	36 f. of 1/2 Deal 3 C of Boat W.		0.. 1.. 6
	a pair of Angus hook & Eye		0.. 10.. 0
	4 Days Work		
	To getting Ang's Ready to put in the Pond to prevent its being Drawn by a Net		0.. 13.. 6
	3/12 f. whole Deals 7 C of Large Tenter-hooks.		1.. 2.. 6
	2 Men 1/2 Days Each		
	To putting a post to fasten the punt to in Pond put on a Chain & Repairing fences round Trees		0.. 1.. 10 1/2
	5 f. of oak 1/2 f. of 1/2		0.. 4.. 4
	2/12 f. whole Deals		0.. 11.. 6
	1/2 C of 20" 1 C of 10" W. & 2 Men 2 Days Each		
	To Mendy the Lathing at the Aviary putting up Stakes & other Jobs.		0.. 2.. 0
	1 Dozen of Portable Laths		0.. 1.. 9
	1/2 C of 6" W. 1 C of Boat W.		0.. 5.. 0
	2 Men 1 Day Each		
	To Repairing the Wainscote of 2 Rooms in Kitchen Garden for W. Staples		0.. 2.. 6
	10 f. of inch Deal 10 f. of Split Deal		0.. 3.. 3
	1 Tash Line 1 C of 10" W. 1/2 C of 20" W.		
	2 C of Brads & Glue		
	1/2 Days Work		0.. 11.. 3
Feb. 26.	To Repairing Rusty Rails in Aha		0.. 3.. 9 1/2
	14 f. of 1/2 f. 5 f. of 1/2		0.. 2.. 4
	1 C of 20" W. 1/2 C of 12" Shill W.		0.. 10.. 0
	2 Men 2 Days Each		0.. 2.. 6
	To the Coloss in the Pond 1 Day		0.. 0.. 9
	1/2 C of Boat W.		
	To fixing Planks to keep up Coals at Xotike Lathouse casing Doors & Lights &c		0.. 5.. 0
	2 Men 1 Day Each		
	To Making 2 Boxes for W. Averfield use		0.. 5.. 10
	2/12 f. 1/2 Deal 1 C of Boat W. 1 Days Work		
	Exp. over		46.. 0.. 0

To Mend 2 Doors Next the Foot Lane, & Mend Doors in Flower Garden & 10 f. of 1/2 Deal 10 f. of whole Deal	46 0 0
1 C of 20. 1/2 C of 10. W. 2 Days Work	0 3 9
To Repairing the Planking at Aviary & Managers & Repairing the Lathing &c	0 6 9
24 f. of 1/2 Deal 3 C of 1/2 of whole Deal	0 17 0
1 C of 20. 1/2 C of 10. Shill. W. 1 C of Boat W.	0 3 4
1 Dozen of Pantile Laths	0 2 0
2 Men 1/2 Day Each	0 7 6
To putt up Shades Mend Doors & Repairing Stages in Leticke hot house &c	0 3 1
1 C of 20. 1/2 C of 10. 1 C of 6. W.	0 10 0
2 Men 2 Days Each	0 5 5
To Repairing the fence by the Ponds side	0 7 6
3/10 f. of 1/2 Deals 1/2 C of 20. W. 1 C of Boat W.	0 7 6
2 Men 1/2 Day Each	0 2 10
To Repairing the fence Next W. Howlets Orchard & putt up New Casings on the Great Gate	0 0 7 1/2
1 pair of oak Rails 10 f. of Split Deal	0 4 2
4 f. 10m Double Deal 4 1/2 wide	3 3 0
2 C of 10. Case & 1 Days Work	
To Making & fixing a Large New Octigonal Seat with a Back to Ditto Round a Tree in the Garden	
To Repairing the fences round Trees & the fence by the pond &c	0 3 2
6 f. of 1/2 Deal 1/12 f. Leaf of Split Deal	0 2 7
1 C of 20. W. 1 C of Boat W. 1/2 C of 6. W.	0 7 6
2 Men 1/2 Day Each	
To Mend Doors & Lathing & putt up Benches At Aviary & Managers &c	0 5 0
12 f. of whole Deal 1 Dozen of pantile Laths	0 2 0
a pair of H. hinges & Screws	0 2 0
1/2 C of 2 Shill. W. 1 C of Boat W.	0 7 6
3 Days Work	
To Mend the Stage in Leticke hot house & Doors to the Store &c	
Car. on	54 14 0 1/2

Sept. 2.

0
9
9
0
4
0
6
1
0
5
6
10
7 1/2
2
0
0
0
0
6
10 1/2

6 ft of Fir of 4 1/2 x 3 1/2 & 2 Shill 1/2 W. 1/2 & 20 W. — 0.. 2.. 0

2 Men 1 Day Each — 0.. 5.. 0

To Mend of the Planking at Manzey in the Lane
Cobhouse door & other jobs
1 & 2 Shill 1/2 W. 1 & 20 W. — 0.. 3.. 4

2 Men 1 Day Each. — 0.. 5.. 0

To Mend of the Rails in Aha
36 ft of Fir of 5 1/2 x 3 1/2 — 0.. 9.. 0

2 Days Work — 0.. 5.. 0

To Making New Pivers to Lights in Kitchen
Garden 16 ft of Elm Board — 0.. 4.. 0

To D. & Mend of Frames & Easing Lights 2 Days — 0.. 5.. 0

To Making Marks for Trees Easing Lights
& Mend of Doors & other jobs in Kitchen Garden
10 ft of Elm Board 1/12 ft of Leaf of Nit coal — 0.. 5.. 0

5 ft of Fir of 4 1/2 x 3 — 0.. 0.. 10

1 & 20. 1/2 & 10. 1 & 6. W. — 0.. 3.. 1

3 Days Work — 0.. 7.. 6

To Repairing Post & Rails in Aha &c
12 ft of 2 1/2 Deal 12 ft of whole Deal. — 0.. 7.. 0

1 & 2 Shill 1/2 W. 1/2 & 20 W. — 0.. 4.. 0

2 Men 4 Days Each. — 1.. 0.. 0

To Mend of the Rails in Cowfield & the
Yard Gates &c
56 ft of Nit Walk 20 Spikes. — 0.. 6.. 4

1/2 & 2 Shill 1/2 W. 1/2 & 20 W. — 0.. 1.. 0

2 Men 1 Day Each. — 0.. 5.. 0

To Mend of the Rails by Lotick Garden &
the fences round the Trees &c
12 ft of whole Deal. — 0.. 3.. 0

2 1/2 & 10. 2 & 6. W. 2 Men 1/2 Day Each — 0.. 9.. 7

1 & 20. W. for W. Aitons use. — 0.. 1.. 4

To the fence by the Pondside putting a Rail
along the Bottom of Spurring &c
2 Men 5 Days Each. — 1.. 5.. 0

To Easing & Mend of Doors & Making Marks
Sticks. Repairing Frames & other jobs in
Kitchen Garden — Car. over 61. 13. 0 1/2

27 9.

27 16.

	Bro. over	61.. 13.. 0 1/2
1/10 of Leaf of Split Deal		0.. 1.. 0
1/2 C of 10. 1/2 C of 20. W. 1 C of Board W. 6 Spikes		0.. 2.. 7
2 Days Work		0.. 5.. 0
To Repairing the Ferry by Lotick Garden & Making Packing Boxes for Mr. Piton & other jobs in hot house		
1/10 of Leaf of Split Deal		0.. 1.. 0
1 C of 20. 1/2 C of 10. 1 C of Board W. 6 Spikes		0.. 3.. 3
2 1/2 Days Work		0.. 6.. 3
To Mending fences round Trees & Darning Doors in Flower Garden & other jobs		
1 C of 10. W. 1 1/2 Days Work		0.. 4.. 7
To Repairing Post & Rails in Aha		
26 of 1/4 of 5 1/2		0.. 6.. 6
12 of 1/4 of 6 1/4		0.. 4.. 0
6 of 1/4 of 4 1/2		0.. 1.. 0
3/10 of Waddens		0.. 4.. 6
1 C of 20. 1 C of 2 Shill. W. 60 Spikes		0.. 8.. 4
6 Days Work		0.. 15.. 0
To the fence by the Pond side &c		
755 of 1/4 of 1/4 Deal 2 in wide for bottom Rail		0.. 15.. 0
100 of 1/4 of Double Deal 2 in wide for Spurs		0.. 0.. 4
36 C of 6. W. 1 C of 10. W.		0.. 18.. 10
2 Men 3 1/2 Days Each		0.. 17.. 6
To Repairing the Post & Rails in Aha		
16 of 1/4 of 4 1/2		0.. 2.. 8
24 of 1/4 of 5 1/2		0.. 6.. 0
10 of 1/4 of 2 1/2 Waddens		0.. 2.. 6
1 C of 2 Shill. W. 1 1/2 C of 20. 1 C of 10. W.		0.. 4.. 10
2 Days Work		0.. 10.. 0
1/4 of 2 Days Work to the Sun Temple		0.. 0.. 7 1/2
To Making Piers for the frames in Kitchen Garden, Darning Doors & Lights at the hot house & other jobs 16 of 1/4 of Elm Board.		
1/2 C of 20. 1/2 C of 10. W. 1/2 C of Board W.		0.. 4.. 0
2 1/2 Days Work		0.. 1.. 7
		0.. 6.. 3
To gett out the Planks & Trusselge at the Green house 2 Men 3 Days Each		
		0.. 15.. 0
		70.. 9.. 10

23.

29

G. W. W. W. W. W. W.
74, 15, 5