

1749=50
Jan. 23

A Bill of Carpenters work done for his
Highness the Prince of Wales in his
Garden at East Ham

	100 of the Stakes for the Garden new stakes new walk	1 lb 0 = 8 = 0
27 th	1/2 a day Taking down posts and rails Moving the old pales by the mount new Straight with the new with an addition of pennells & digging out the old marks & set 1 new post & 1/2 of rails & 19 new pales one day & 1/2 2 men and 1 lb of 10 nails	0 = 1 = 1
29 th	Raising the pales at the corner of mount people getting over 16-5 foot pales & one 10 foot che nail 1 days work & 1 lb & 1/2 of 10 nails	0 = 4 = 2 0 = 3 = 10
	To a Scaffold where the Chinese Temple now stands for his Royal Highness to see what he pleased the use of 8 Beams 30 deals & ropes 2 men 2 days work each & 1 lb of 20 nails	0 = 15 = 0 0 = 7 = 0
March 17 th	To Building a Scaffold in the warren field to the South & removing it to the north side of the field the use of 8 poles 10-16 foot deals & 10 choal deals 2 Days & 1/2 work 2 men & 30 Spikes	0 = 16 = 0 0 = 9 = 6
	1/2 a days work moving posts in Salters ground	0 = 1 = 5
21 st	Repairing pales by stable yard gate 4 che pales 3 foot of rail Labour and nails	0 = 2 = 0
23 rd	Taking down the scaffold in the warren 1/2 a days work 2 men	0 = 2 = 10
27 th	6 Stakes of oak for 1/2 a day 2 men to help stake it out	0 = 5 = 10
April 4	Altering the stakes to fofes 4 Stakes & 1/2 a day 2 men to help stake it out 3 Boncing Sticks	0 = 4 = 10 0 = 1 = 6
19	Shooping up the garden wall several times when when it was through the use of Shoars and blocks	0 = 4 = 0
		5 = 4 = 5

Brought over 5 = 4 =

2 men 3 days each 0 = 17 =

To the Icehouse 0 = 8 =

10 foot of plank & 10 foot of deal 0 = 5 =

300 of 20# nails 0 = 17 =

300 of 20# nails 0 = 17 =

100 of 20# nails 0 = 17 =

100 of 20# nails 0 = 17 =

100 of 20# nails 0 = 17 =

100 of 20# nails 0 = 17 =

100 of 20# nails 0 = 17 =

100 of 20# nails 0 = 17 =

100 of 20# nails 3 = 15 =

100 of 20# nails 3 = 15 =

May 10th Putting rails by the Icehouse 0 = 3 =

24 foot runn of Board & labour & nails 0 = 3 =

Preparing a Garden Seat 0 = 4 =

6 foot of oak Board & 3/4 of # of 20 nails 0 = 4 =

1 Day and 1/2 work 0 = 4 =

To a Table & Benches for the workmen to dine on 0 = 4 =

when the ox was roasted 0 = 4 =

320 foot runn of Board cut into short pieces for tables & benches 1 = 6 =

the use of 54 - 16 foot deals at 1/4 foot 0 = 18 =

7 men one days work each 0 = 19 =

30 20# nails 0 = 19 =

Taking the above down and removing the materials 0 = 4 =

7 men 1/2 a day each 0 = 9 =

Putting up 16 Canvas shade in the warren 0 = 4 =

8 pieces of white deal 10 foot long & nails 0 = 5 =

2 men one day each to that and other jobs 0 = 5 =

Taking down the Scaffold in the warren and removing 0 = 5 =

the materials 0 = 5 =

Putting on a lock 0 = 5 =

17 = 18 = 1